

**** An URGENT REMINDER about Moose wing torque tube safety wire locking**

We have had some indications that not all owners/builders of the **Super Rebel** and **Moose** are aware of the **Service Bulletin** about wire locking the bolt on the aileron torque tube, dated **Oct. 10, 2005**.

Here is a link to the **Moose Tech Support page**:

<http://www.pattersonaerosales.com/Aircraft/Moose/MooseTechSpt.html>

All builders should review ALL of the bulletins, to be sure they have been complied with.

Here's a link directly to the PDF of the aileron torque tube bulletin:

http://www.pattersonaerosales.com/Aircraft/Moose/TechSpt/Service_Bulletin_Oct1005.pdf