

**** An URGENT REMINDER about SR Series and Elite elevator mods S/B compliance**

We have had indications that some owners/builders of the **Super Rebel** and **Moose**, as well as the **Elite** have **NOT** followed the **Service Bulletin** about **elevator mods**, dated **Nov. 4, 2004**.

Particularly important is the installation of the large surface doubler shown in Fig. 9, which would be good for the Elite as well.

Here is a link to the **Moose Tech Support page**:

<http://www.pattersonaerosales.com/Aircraft/Moose/MooseTechSpt.html>

All builders should review ALL of the bulletins, to be sure they have been complied with.

Here's a link directly to the Moose PDF of the elevator mod bulletin:

http://www.pattersonaerosales.com/Aircraft/Moose/TechSpt/CH_13_SR3500_elevator.pdf

Here is a link to the **Elite Tech Support page**:

<http://www.pattersonaerosales.com/Aircraft/Elite/EliteTechSpt.html>

All builders should review ALL of the bulletins, to be sure they have been complied with.

Here's a link directly to the original Elite PDF of the elevator mod bulletin:

<http://www.pattersonaerosales.com/Aircraft/Elite/TechSpt/ELEVHORN.pdf>